

ASBESTOS POLICIES

1. All contractors/haulers must have an active account with PVT Land Company, Ltd. (PVT). Contractor and hauler must provide a local telephone number for emergency purposes.
2. All asbestos contractors must comply with the following conditions:
 - a. All asbestos containing material (ACM) that is brought into PVT is required to be prepared properly for disposal.
 - b. All ACM must be thoroughly wet down or encapsulated prior to containment by the operator preparing the debris for disposal.
 - c. All ACM is to be double bagged or double wrapped in a minimum of 6mm thick plastic. The operator shall make every reasonable effort to avoid the release of any ACM at the landfill while unloading.
 - d. All properly contained ACM must display **asbestos hazard warning labels** as well as labels that have the owner's name, address and telephone number.
 - e. Any chemical (e.g. solvent used to remove VAT mastic) added to the ACM waste is required to be pre-approved by PVT prior to acceptance for disposal.
 - f. A properly executed Asbestos Waste Shipment Record must accompany all loads of ACM.
 - g. All other applicable state and federal regulations concerning this waste stream must be met prior to acceptance of disposal. It is the responsibility of the generator to know and comply with these regulations.
3. Asbestos will be accepted on **Tuesday and Thursday only**, unless canceled because of inclement weather or for safety reasons. PVT may determine another day as needed.
4. All Asbestos loads must be scheduled at least 24 hours before delivery. PVT has the right to turn away any load that is not scheduled.
5. Each asbestos load must be accompanied by a manifest. The operator and the driver hauling the load must sign the manifest.

NO MANIFEST=NO DUMPING
6. Each asbestos load accepted for dumping will be escorted and directed where to dump. Escort is to stand a safe distance away from unloading area and truck, while viewing load disposal.
7. Only ACM, doubled wrapped in 6mm plastic will be allowed in the asbestos pit.
8. If the asbestos load breaks open upon disposal and ACM is exposed, the PVT escort will notify the contractor, who will then be required to send a qualified individual to the landfill to cover the exposed area before the end of that day.
9. Last asbestos loads must be on the scale by 1:00 pm. Last hand unloads for asbestos loads must be on the scale by 12:30 pm. Scheduled loads that are not received will require re-scheduling for future delivery and acceptance.
10. The Weigh Master for PVT will be responsible for signing asbestos waste manifest, printing tag and returning copies to driver. Each load of asbestos received will then be logged into the daily log sheet, identifying contractor and jobsite. All tags with proper manifest attached will be filed for record purposes.
11. All asbestos will be covered at the end of the day. No bags are left exposed.