



POLICIES AND PROCEDURES FOR ASBESTOS DISPOSAL

Landfill hours. The landfill will only accept asbestos on Tuesdays and Thursdays from 7:00 am to 1:30 pm. All asbestos loads must be scheduled twenty-four (24) hours before delivery. Last asbestos loads must be on the scale by 1:30 pm. Last hand unloads for asbestos loads must be on the scale by 1:30 pm. Scheduled loads that are not received by the required time will require re-scheduling for future delivery and acceptance. Landfill hours of operation are subject to change without notice; PVT reserves the right to close the landfill at any time for any purpose, including but not limited to rain, high winds, and repair and maintenance.

Permitted Asbestos Materials. User may dispose non-friable and friable asbestos, such as roofing, ceiling and insulating materials, and fixed asbestos, with required Agreements and pre-approvals.

Asbestos Containment and Labelling. All asbestos containing material ("ACM") that is brought into landfill is required to be prepared for disposal as though the ACM were friable, even if it has been determined to be non-friable. All ACM must be thoroughly wet down or encapsulated prior to containment by the operator preparing the debris for disposal. All ACM must be double bagged or double wrapped in plastic with a minimum thickness of six (6) millimeters, or contained in sealed drums or barrels. All bagged, wrapped, or contained ACM must display asbestos hazard warning labels, as well as labels that have the owner's name, address and telephone number. Any chemical (e.g., solvent used to remove VAT mastic) added to the ACM waste must be pre-approved by the landfill's Operation Manager prior to acceptance for disposal.

Asbestos Pre-approval. PVT will accept ACM on a prearranged basis only. A Request for Clearance Number form and an Asbestos Notification of Demolition and Renovation form must be completed and submitted to the PVT Office in advance of any ACM being accepted for disposal. All asbestos loads must be scheduled twenty-four (24) hours before delivery and accompanied by a properly executed Asbestos Waste Shipment Record. Each Asbestos Waste Shipment Record must be signed by both the operator and transporter hauling the ACM to the landfill. No disposal will be allowed without a complete Asbestos Waste Shipment Record. All other applicable State and Federal Regulations concerning this waste stream must be met prior to acceptance of this waste stream for disposal. It is the responsibility of the User to know and comply with these regulations.

Asbestos Contractors and Transporters. All asbestos contractors and transporters must have an active account with PVT. All contractors and transporters must provide a local telephone number for emergency purposes.

Asbestos Disposal. Each asbestos load accepted for disposal will be escorted and directed where to unload. The PVT escort will stand a safe distance away from the unloading area and truck, while viewing the load disposal. The transporter must make every reasonable effort to avoid the release of any ACM at the landfill. A qualified individual must accompany the load and observe disposal. If the asbestos load breaks open upon disposal and ACM is exposed, the qualified individual must cover the exposed area promptly. All asbestos will be covered at the end of the day. No bags will be left exposed.

Asbestos Records. The Weigh Master for PVT will be responsible for signing the Asbestos Waste Shipment Record, printing a tag and returning copies to the driver.

PVT's Right of Rejection. PVT reserves the right to reject any load where PVT believes, for any reason, said load may contain Prohibited Materials. PVT reserves the right to reject any load which may be a violation of its solid waste permit or any laws, rules or regulations (federal, state or local) now or hereafter in effect, or any load which would adversely impact the landfill.